










PART LIST

NO.	Picture	Specification	Qty
A		Screws $\text{Ø}3*1/2''$	32
B		Screws $\text{Ø}4*1''$	6
C		Metal Clip	8



PR3018

Unit: inch

<p>1</p>  <p>Face frame</p>	<p>2</p>  <p>Left Side Panel</p>	<p>3</p>  <p>Right Side Panel</p>	<p>4</p>  <p>Back Board</p>	<p>5</p>  <p>Top Panel</p>
<p>6</p>  <p>Bottom Panel</p>	<p>7</p>  <p>Plate Rack</p>	 <p>Plate Rack</p>		

Assembly instructions

NO.	PICTURE	SIZE	QTY
A		Screws $\text{\O}3*1/2''$	32
B		Screws $\text{\O}4*1''$	6
C		Metal Clip	8

