




NO	Picture	Specification	Qty
A		Screws $\varnothing 4 \times 1 \frac{3}{16}$ "	20

1


Left
Side Panel

2


Right
Side Panel

3


Top
Panel

4


Bottom
Panel


5

Shelf


			 A	

Assembly instructions


NO	Picture	Specification	Qty
A		Screws $\varnothing 4 * 1 \frac{3}{16}$ "	20




step 1



step 2



step 3



step 4